

April 06



NOTE 11  
ASI5111 Rev C

---

NOV/14/05

The ASI5111 revision C requires a driver revision of 2.95 or higher.

Please download it from [www.audioscience.com](http://www.audioscience.com).

There are no functionality changes from previous revisions of the ASI5111.

<end>